PRINT DATE: 04/11/98

FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL HARDWARE NUMBER:M5-6\$\$-0606 -X

SUBSYSTEM NAME: ISS DOCKING SYSTEM

REVISION: 0

02/27/98

PART DATA

PART NAME

VENDOR NAME

PART NUMBER

VENDOR NUMBER

LRU

:AW18H PANEL

VO75-730151

SRU

:TOGGLE SWITCH

ME452-0102-7803

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:

TOGGLE SWITCH, 3 POLE, 3 POSITION, CENTER OFF - EXTERNAL AIRLOCK EMU 1 AND 2 MODE (POWER-OFF-CHARGE)

REFERENCE DESIGNATORS:

84V73A133S3

84V73A133S5

QUANTITY OF LIKE ITEMS: 2

(TWO):

FUNCTION:

ALLOWS CHARGING OF EXTRAVEHICULAR MOBILITY UNIT (EMU) BATTERY OR SWITCHES POWER DIRECTLY TO EMU.

REFERENCE DOCUMENTS:

1) VS70-960099, INTEGRATED SCHEMATIC - 60DF1.

AECS EXTRAVEHICULAR MOBILITY UNIT/EXT AIRLOCK

FAILURE MODES EFFECTS ANALYSIS FMEA - NON-CIL FAILURE MODE

NUMBER: M5-68S-0606-01

REVISION#: 0

02/27/98

SUBSYSTEM NAME: ISS DOCKING SYSTEM

LRU: AW18H PANEL -

CRITICALITY OF THIS

FAILURE MODE: 1R3

FAILURE MODE:

FAIL OPEN, SHORT-TO-CASE (GROUND)

ITEM NAME: TOGGLE SWITCH

MISSION PHASE:

OO ON-ORBIT

VEHICLE/PAYLOAD/KIT EFFECTIVITY:

103 DISCOVERY

104 ATLANTIS

105 ENDEAVOUR

CAUSE:

A) PIECE PART STRUCTURAL FAILURE, B) CONTAMINATION, C) VIBRATION, D) MECHANICAL SHOCK, E) PROCESSING ANOMALY, F) THERMAL STRESS

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

CRITICALITY 1R2 DURING INTACT ABORT ONLY (AVIONICS ONLY)? NO

REDUNDANCY SCREEN

A) PASS

B) PASS

C) PASS

PASS/FAIL RATIONALE:

A)

B)

C)

CORRECTING ACTION: NONE

CORRECTING ACTION DESCRIPTION:

DESIGN FAULT TOLERANCE: SWITCH OF OTHER EMU POWER SLIPPLY AND BATTERY CHARGER REMAINS OPERATIONAL - CAN SERVICE BOTH EMU'S FROM REMAINING SERVICE POINT.

PAGE: 3 PRINT DATE: 04/11/98

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- NON-CIL FAILURE MODE NUMBER: M5-85S-0606-01

- FAILURE EFFECTS -

(A) SUBSYSTEM:

LOSS OF CAPABILITY TO PROVIDE POWER TO ONE OF TWO EMU POWER CONNECTIONS IN THE EXTERNAL AIRLOCK.

(B) INTERFACING SUBSYSTEM(S):

CANNOT CHARGE EMU BATTERY OR POWER AN EMU FROM ONE OF TWO EMU POWER CONNECTIONS IN THE EXTERNAL AIRLOCK.

(C) MISSION:

FIRST FAILURE - NO EFFECT

(D) CREW, VEHICLE, AND ELEMENT(\$):

FIRST FAILURE - NO EFFECT

(E) FUNCTIONAL CRITICALITY EFFECTS:

POSSIBLE LOSS OF CREWIVEHICLE AFTER FOUR FAILURES:

- 1) SWITCH FAILS OPEN LOSS OF EMU POWER SUPPLY AND BATTERY CHARGER CAPABILITIES TO ONE EMU.
- 2) SECOND SWITCH FAILS OPEN LOSS OF EMU POWER SUPPLY AND BATTERY CHARGER CAPABILITIES TO ALL EMU'S. WORST CASE IF FAILURE OCCURS FOLLOWING AN INITIAL EVA WHERE SUBSEQUENT EVA MUST BE PERFORMED USING ONE EMU WITH THE SPARE BATTERY PACK.
- LOSS OF THE SPARE BATTERY PACK FOR BOTH EMU'S LOSS OF BOTH EMU'S WOULD PRECLUDE SUBSEQUENT EVA CAPABILITIES.
- 4) A FAILURE NECESSITATING AN EVA TO PREVENT A POTENTIAL CATASTROPHIC SITUATION INABILITY TO PERFORM A CONTINGENCY EVA TO CORRECT A CRIT 1 CONDITION COULD RESULT IN LOSS OF CREW/VEHICLE.

DESIGN CRITICALITY (PRIOR TO DOWNGRADE, DESCRIBED IN (F)):

(F) RATIONALE FOR CRITICALITY DOWNGRADE:

ALTHOUGH THE CRITICALITY REMAINS UNCHANGED AFTER WORKAROUNDS CONSIDERATION (ALLOWED PER CR \$050107W), THEY ARE PROVIDING ADDITIONAL FAULT TOLERANCE TO THE SYSTEM.

AFTER THE FOURTH FAILURE (FAILURE NECESSITATING AN EVA TO PREVENT A POTENTIAL CATASTROPHIC SITUATION) - INABILITY TO PERFORM CONTINGENCY EVA (FIFTH FAILURE) TO CORRECT A CRIT 1 CONDITION COULD RESULT IN LOSS OF CREW AND VEHICLE.

PRINT DATE: 04/11/98

PAGE: 4

FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL FAILURE MODE NUMBER: M5-6SS-0806-01

- TIME FRAME -

TIME FROM FAILURE TO CRITICAL EFFECT: DAYS

TIME FROM FAILURE OCCURRENCE TO DETECTION: DAYS

TIME FROM DETECTION TO COMPLETED CORRECTING ACTION: N/A

IS TIME REQUIRED TO IMPLEMENT CORRECTING ACTION LESS THAN TIME TO EFFECT?

RATIONALE FOR TIME TO CORRECTING ACTION VS TIME TO EFFECT:

AFTER THE FIRST FAILURE, THE SECOND POWER SUPPLY AND BATTERY CHARGER SERVICE POINT IS OPERATIONAL ON THE SERVICE CONNECTION UNIT. THE CREW CAN ALTERNATE THE EMU'S ON THIS OPERATIONAL SERVICE POINT TO CHARGE THE BATTERIES.

HAZARD REPORT NUMBER(S): NONE

HAZARD(S) DESCRIPTION:

NONE

- APPROVALS -

SS&PAE

: T. K. KIMURA

DESIGN ENGINEERING

: C. J. ARROYO